

BMW Commander 3.1

	Price / Euro
BMW-Base interface (identification,error memory, synchronization, program ID, Enable TV, reset service intervals, dump tool)	798
SW update "Memory manager" (except CAS)	300
SW update "CAS1 E65 and CAS2" (odometer correction, eeprom R/W, key coding)	246
SW update "CAS3" (odometer correction, eeprom R/W, key coding)	246

Note:

- * Base interface need to be in your configuration in every case
- * Owners of VAG K+CAN Commander can update his interface to BMW base interface. Price of update is 396 euro.All prices are with VAT 20% included